

POPCORN POPPING INSTRUCTIONS

1. Make sure popcorn stand is on a flat surface near an electrical outlet or extension cord
2. Turn machine on and allow to heat for 3-5 minutes. Once heated, turn off.
3. Add oil to the kettle - popcorn specific oil or vegetable oil - (see measurements below) then add popcorn.
4. Close door and turn machine back on.
5. Once popping has stopped, turn machine off.
6. Turn gold handle to dispense popcorn underneath main compartment, or use supplied scoop.

POPCORN / OIL MEASUREMENTS

8oz popcorn to 4 tablespoons oil.

** Use no more than 4 tablespoons of oil per batch of popcorn

